

Bar Height Table

ASSEMBLY INSTRUCTIONS



LANCASTER™
TABLE & SEATING


ALLOY Series

PARTS LIST

A Table Top



C (4) Table Legs



B Support Bar



HARDWARE

D M6 Allen Key



E (16) M6x12 Screws



F (4) M6x25 Screws




NOTES

- Inspect all pieces for damage before assembly. Do not assemble if any pieces are broken or damaged. Ensure you have all required pieces before assembly.
- Power drill is optional for assembly.
- Graphics of images are shown with a square table top, but assembly is the same for all table top shapes (rectangular, square, and round).

STEP 1


Place table top (A) upside down on a flat, clean surface.

Attach one table leg (C) to the corner of the table top. Hold the leg against the corner and find the four threaded holes on the table top. Use (4) M6x12 screws (E) to secure the leg to the table top using the provided allen key (D).



STEP 2

Repeat the previous step for the remaining three legs. Do not fully tighten screws yet.



Bar Height Table

ASSEMBLY INSTRUCTIONS




LANCASTER™
TABLE & SEATING

ALLOY Series

STEP 3

Place support bar (B) between all four legs. Locate the four holes on the inside of each leg.

Secure support bar to table legs using the (4) M6x25 screws (F) and allen key (D). Insert screws through the support bar and into the table leg for each of the four holes. Fully tighten using the allen key (D).



STEP 4

Fully tighten all 16 screws on the table top and table legs.

Stand the table upright and ensure it is stable and level.

